



Technical Service Bulletin

Technical Service Bulletin: tsb101872

Released Date: 05-May-2006

Revision to Procedure Piston and Connecting Rod Assembly, New Torque Procedure

Revision to Procedure Piston and Connecting Rod Assembly, New Torque Procedure

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic revises, Procedure 001-054, Piston and Connecting Rod Assembly. The torque procedure has been revised

Note : This is a product improvement and not subject to campaign.

Related Procedures

56-001-054
(/qs3/pubsys2/xml/en/procedures/56/56-001-054.html)

Piston and Connecting Rod Assembly
(/qs3/pubsys2/xml/en/procedures/56/56-001-054.html)

Last Modified: 05-May-2006