



Technical Service Bulletin

Technical Service Bulletin: tsb101885

Released Date: 19-Jul-2006

Engine Testing (Engine Dynamometer)

Engine Testing (Engine Dynamometer)

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic provides information on the revision of Procedures 014-005 and 014-006, Engine Testing (Engine Dynamometer) for the QSK45 and QSK60 series engines. This topic updates the procedure for the use of the engine control, the INLINE™ 5 datalink adapter kit, and the engine control harness installation on electronically actuated injector engines.

Related Procedures

56-014-005-tr (/qs3/pubsys2/xml/en/procedures/56/56-014-005-tr.html)	Engine Testing (Engine Dynamometer) (/qs3/pubsys2/xml/en/procedures/56/56-014-005-tr.html)
56-014-006-tr (/qs3/pubsys2/xml/en/procedures/56/56-014-006-tr.html)	Engine Run-in (Engine Dynamometer) (/qs3/pubsys2/xml/en/procedures/56/56-014-006-tr.html)

Last Modified: 19-Jul-2006