



Technical Service Bulletin

Technical Service Bulletin: tsb101978

Released Date: 19-Oct-2006

Revision to Engine Diagrams Procedure

Revision to Engine Diagrams Procedure

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic adds five views of the QSK60 single stage with electronically actuated injectors.

Related Procedures

56-100-002-om-rep
(/qs3/pubsys2/xml/en/procedures/56/56-100-002-om-rep.html)

Engine Diagrams
(/qs3/pubsys2/xml/en/procedures/56/56-100-002-om-rep.html)

Last Modified: 19-Oct-2006