



Technical Service Bulletin

Technical Service Bulletin: tsb102042

Released Date: 15-Nov-2006

Revision to Install Step in Cylinder Liner Procedure

Revision to Install Step in Cylinder Liner Procedure

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic revises sealant, Part Number 3165150, in the Install Step in Cylinder Liner Procedure 001-028. The new sealant Part Number is 4918771.

Related Procedures

56-001-028
(/qs3/pubsys2/xml/en/procedures/56/56-001-028.html)

Cylinder Liner
(/qs3/pubsys2/xml/en/procedures/56/56-001-028.html)

Last Modified: 15-Nov-2006