



Technical Service Bulletin

Technical Service Bulletin: tsb102053

Released Date: 14-Nov-2006

Spin-on Fuel Filter Procedure Update for Electronically Actuated Injectors

Spin-on Fuel Filter Procedure Update for Electronically Actuated Injectors

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic updates Procedure 006-015, Fuel Filter, Spin-on, for QSK45 and QSK60 industrial and marine series engines with electronically actuated injectors.

Related Procedures

56-006-015-tr
(/qs3/pubsys2/xml/en/procedures/56/56-006-015-tr.html)

Fuel Filter (Spin-On Type)
(/qs3/pubsys2/xml/en/procedures/56/56-006-015-tr.html)

Last Modified: 14-Nov-2006