



Technical Service Bulletin

Technical Service Bulletin: tsb102055

Released Date: 21-Nov-2006

Revised Fuel Lift Pump Procedure, Filtration System Update

Revised Fuel Lift Pump Procedure, Filtration System Update

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic revises Procedure 005-045, Fuel Lift Pump, for QSK60 series engines with electronically actuated injectors, due to changes in the filtration system.

Related Procedures

56-005-045-tr
(/qs3/pubsys2/xml/en/procedures/56/56-005-045-tr.html)

Fuel Lift Pump
(/qs3/pubsys2/xml/en/procedures/56/56-005-045-tr.html)

Last Modified: 21-Nov-2006