



Technical Service Bulletin

Technical Service Bulletin: tsb102076

Released Date: 11-Dec-2006

Revision, Multiple Steps, Fuel Pump Procedure

Revision, Multiple Steps, Fuel Pump Procedure

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic updates Procedure 005-016 Fuel Pump for the QSK60 engine with electronically actuated injectors.

Related Procedures

56-005-016
(/qs3/pubsys2/xml/en/procedures/56/56-005-016.html)

Fuel Pump
(/qs3/pubsys2/xml/en/procedures/56/56-005-016.html)

Last Modified: 11-Dec-2006