



Technical Service Bulletin

Technical Service Bulletin: tsb102077

Released Date: 12-Dec-2006

New Procedure, Fuel Pump Pressurizing Assembly

New Procedure, Fuel Pump Pressurizing Assembly

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic introduces a new common Procedure 005-232, Fuel Pump Pressurizing Assembly, to be used in the QSK60 modular common rail system engines.

Related Procedures

102-005-232
(/qs3/pubsys2/xml/en/procedures/102/102-005-232.html)

GROUPNUM 005 PROCNUM 232
(/qs3/pubsys2/xml/en/procedures/102/102-005-232.html)

Last Modified: 12-Dec-2006