



Technical Service Bulletin

Technical Service Bulletin: tsb102183

Released Date: 15-Mar-2007

Revision, Loading Information, Engine Run-In (Engine Dynamometer) Procedure 014-006

Revision, Loading Information, Engine Run-In (Engine Dynamometer) Procedure 014-006

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic advises the service channel of changes to the Engine Run-in (Engine Dynamometer) procedure for the QSK45 and QSK60 Service Manual. This change introduces a chart for determining the run-in load for QSK45 and QSK60 engines.

Related Procedures

56-014-006-tr
(/qs3/pubsys2/xml/en/procedures/56/56-014-006-tr.html)

Engine Run-in (Engine Dynamometer)
(/qs3/pubsys2/xml/en/procedures/56/56-014-006-tr.html)

Last Modified: 15-Mar-2007