



Technical Service Bulletin

Technical Service Bulletin: tsb102253

Released Date: 07-May-2007

Revision, Measure Step, Cylinder Block Procedure

Revision, Measure Step, Cylinder Block Procedure

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic updates Procedure 001-026, Cylinder Block, to show the correct minimum value for the lower counterbore inside diameter (Lower Press Fit).

Related Procedures

56-001-026
(/qs3/pubsys2/xml/en/procedures/56/56-001-026.html)

Cylinder Block
(/qs3/pubsys2/xml/en/procedures/56/56-001-026.html)

Last Modified: 07-May-2007