



Technical Service Bulletin

Technical Service Bulletin: tsb102282

Released Date: 05-Jun-2007

Revision, Measure Step, Fuel Inlet Restriction Procedure

Revision, Measure Step, Fuel Inlet Restriction Procedure

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic revises the measure step in Procedure 006-020 (Fuel Inlet Restriction) in Section 6 of the QSK45 and QSK60 Service Manual, Bulletin 4021530.

Related Procedures

56-006-020-tr
(/qs3/pubsys2/xml/en/procedures/56/56-006-020-tr.html)

Fuel Inlet Restriction
(/qs3/pubsys2/xml/en/procedures/56/56-006-020-tr.html)

Last Modified: 05-Jun-2007