



Technical Service Bulletin

Technical Service Bulletin: tsb102339

Released Date: 11-Jul-2007

Revision, Initial Check Step, Injector Procedure

Revision, Initial Check Step, Injector Procedure

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic revises Procedure 006-026 (Injector) in Section 6 of the Service Manual, QSK45 and QSK60, Bulletin 4021530. The procedure is being revised to add information on how to determine if the high-pressure injection (HPI) injectors have run dry (without fuel) and to check the engine.

Related Procedures

56-006-026-tr
(/qs3/pubsys2/xml/en/procedures/56/56-006-026-tr.html)

Injector
(/qs3/pubsys2/xml/en/procedures/56/56-006-026-tr.html)

Last Modified: 11-Jul-2007