



Technical Service Bulletin

Technical Service Bulletin: tsb102368

Released Date: 11-Jul-2007

Addition, Service Tool Procedure

Addition, Service Tool Procedure

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic adds service tools Fluorescent Tracer Dye and Black Light Lamp Kit to the Service Tools Procedure 022-001_08 in Section 8.

Note : This is a product improvement and is not subject to campaign.

Related Procedures

56-022-001_08-tr
(/qs3/pubsys2/xml/en/procedures/56/56-022-001_08-tr.html)

Service Tools
(/qs3/pubsys2/xml/en/procedures/56/56-022-001_08-tr.html)

Last Modified: 11-Jul-2007