



Technical Service Bulletin

Technical Service Bulletin: tsb102388

Released Date: 06-Jul-2007

Revision, Install Step, Idler Gear, Camshaft (Right Bank) Procedure

Revision, Install Step, Idler Gear, Camshaft (Right Bank) Procedure

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

The purpose of this Service/Parts Topic is to correct the positioning of the oil hole when assembling the right bank camshaft idler shaft on the QSK45 and QSK60 engine, Procedure 001-038 (Idler Gear, Camshaft (Right Bank)) in Section 1. (</qs3/pubsys2/xml/en/procedures/56/56-001-038-tr.html>)

Related Procedures

56-001-038
(</qs3/pubsys2/xml/en/procedures/56/56-001-038.html>)

Idler Gear, Camshaft (Right Bank)
(</qs3/pubsys2/xml/en/procedures/56/56-001-038.html>)

Last Modified: 06-Jul-2007