



Technical Service Bulletin

Technical Service Bulletin: tsb102445	Released Date: 04-Sep-2007
Revision to Troubleshooting Trees t022, t023, t024, and t096	

Revision to Troubleshooting Trees t022, t023, t024, and t096

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic revises the following troubleshooting trees for the QSK45 and QSK60 engines:

- 4021530-t022 - Coolant Temperature Above Normal - Gradual Overheat
- 4021530-t023 - Coolant Temperature Above Normal - Sudden Overheat
- 4021530-t024 - Coolant Temperature Below Normal
- 4021530-t096 - Intake Manifold Air Temperature Above Specification.

Note : This is a product improvement and is not subject to campaign.

Coolant Temperature Above Normal - Gradual Overheat Coolant Temperature Above Normal - Sudden Overheat Coolant Temperature Below Normal Intake Manifold Air Temperature Above Specification

Last Modified: 04-Sep-2007
