



Technical Service Bulletin

Technical Service Bulletin: tsb102457	Released Date: 05-Dec-2007
Revision, Symptom Tree t027, Crankcase Gases (Blowby) Excessive	

Revision, Symptom Tree t027, Crankcase Gases (Blowby) Excessive

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic revises symptom tree t027, Crankcase Gases (Blowby) Excessive.

Note : This is a product improvement and is not subject to campaign.

Crankcase Gases (Blowby) Excessive

Last Modified: 05-Dec-2007
