



Technical Service Bulletin

Technical Service Bulletin: tsb102484

Released Date: 14-Sep-2007

Revision, Inspect Step, Lubricating Oil Filter (Spin-On) Procedure

Revision, Inspect Step, Lubricating Oil Filter (Spin-On) Procedure

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic revises 007-013 (Lubricating Oil Filter (Spin-On)) the Inspect step to include aftercooler fretting as a possible location for aluminum in the oil.

Related Procedures

56-007-013
(/qs3/pubsys2/xml/en/procedures/56/56-007-013.html)

Lubricating Oil Filter (Spin-On)
(/qs3/pubsys2/xml/en/procedures/56/56-007-013.html)

Last Modified: 14-Sep-2007