



Technical Service Bulletin

Technical Service Bulletin: tsb102500

Released Date: 23-Oct-2007

Addition, Single and Double Nut Configuration Rebuild Instructions, (Fan Hub, Belt Driven) Procedure

Addition, Single and Double Nut Configuration Rebuild Instructions, (Fan Hub, Belt Driven) Procedure

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic adds single nut (406 mm [15.98 in] diameter hub) and double nut (450 mm [17.72 in] diameter hub) configuration rebuild instructions to Procedure 008-036 (Fan Hub, Belt Driven).

Related Procedures

56-008-036-tr
(/qs3/pubsys2/xml/en/procedures/56/56-008-036-tr.html)

Fan Hub, Belt Driven
(/qs3/pubsys2/xml/en/procedures/56/56-008-036-tr.html)

Last Modified: 23-Oct-2007