



# Technical Service Bulletin

Technical Service Bulletin: tsb102506

Released Date: 23-Oct-2007

Revision, Measure Step, Cylinder Block and Liner Seats Procedure

## Revision, Measure Step, Cylinder Block and Liner Seats Procedure

### Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

### Contents

This Service/Parts Topic revises Procedure 001-027 (Cylinder Block and Liner Seats) in Section 1 of the QSK45 and QSK60 Service Manual, Bulletin 4021530. Oversize liners have been included.

### Related Procedures

56-001-027  
(/qs3/pubsys2/xml/en/procedures/56/56-001-027.html)

Cylinder Block and Liner Seats  
(/qs3/pubsys2/xml/en/procedures/56/56-001-027.html)

Last Modified: 23-Oct-2007