



Technical Service Bulletin

Technical Service Bulletin: tsb102510

Released Date: 30-Oct-2007

Complete Revision, Sensor Wiring Harness Procedure

Complete Revision, Sensor Wiring Harness Procedure

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic adds the content from Procedures 019-043 (Engine Wiring Harness) to 019-081 (Sensor Wiring Harness). In addition, wiring harness bracket and cover torques have been included. Procedure 019-043 (Engine Wiring Harness) is no longer included in the Troubleshooting and Repair Manual, CENSE™ System, QSK45 and QSK60 Engine Series, Bulletin 3666410.

Related Procedures

81-019-081

(/qs3/pubsys2/xml/en/procedures/81/81-019-081.html)

Sensor Wiring Harness

(/qs3/pubsys2/xml/en/procedures/81/81-019-081.html)

Last Modified: 30-Oct-2007