



Technical Service Bulletin

Technical Service Bulletin: tsb102513

Released Date: 02-Nov-2007

Revision, Install Step, Injector Procedure

Revision, Install Step, Injector Procedure

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic revises the torque value of the mechanically actuated injector hold-down capscrew in Procedure 006-026 (Injector). The new torque value for the injector hold-down capscrew is 75 N·m [55 ft-lb].

Related Procedures

56-006-026-tr
(/qs3/pubsys2/xml/en/procedures/56/56-006-026-tr.html)

Injector
(/qs3/pubsys2/xml/en/procedures/56/56-006-026-tr.html)

Last Modified: 02-Nov-2007