



Technical Service Bulletin

Technical Service Bulletin: tsb102530

Released Date: 02-Nov-2007

Revision, Preparatory Step, Engine Run-in (Without Dynamometer) Procedure

Revision, Preparatory Step, Engine Run-in (Without Dynamometer) Procedure

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

The purpose of this Service/Parts Topic is to revise the Preparatory Step for Procedure 014-004, Engine Run-in (Without Dynamometer). The requirements to pre heat the engine and the use of SAE 10W-30 lubricating oil has been removed.

Related Procedures

56-014-004-tr
(/qs3/pubsys2/xml/en/procedures/56/56-014-004-tr.html)

Engine Run-in (Without Dynamometer)
(/qs3/pubsys2/xml/en/procedures/56/56-014-004-tr.html)

Last Modified: 02-Nov-2007