



Technical Service Bulletin

Technical Service Bulletin: tsb102557

Released Date: 30-Nov-2007

Revision, Assembly Step, Fan Drive Idler Arm Assembly Procedure

Revision, Assembly Step, Fan Drive Idler Arm Assembly Procedure

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This purpose of this Service/Parts Topic is revise the assembly step in Procedure 008-029 (Fan Drive Idler Arm Assembly) in Group 8. The procedure now includes a slide arm design idler assembly.

Related Procedures

56-008-029-tr
(/qs3/pubsys2/xml/en/procedures/56/56-008-029-tr.html)

Fan Drive Idler Arm Assembly
(/qs3/pubsys2/xml/en/procedures/56/56-008-029-tr.html)

Last Modified: 30-Nov-2007