



Technical Service Bulletin

Technical Service Bulletin: tsb102618

Released Date: 19-Dec-2007

Revision, Torque Value, (Bearings, Main) and Crankshaft Procedures

Revision, Torque Value, (Bearings, Main) and Crankshaft Procedures

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic revises the torque specification for main bearing side bolts in Procedures 001-006 (Bearings, Main) and 001-016 (Crankshaft) in Section 1.

Related Procedures

56-001-006-tr (/qs3/pubsys2/xml/en/procedures/56/56-001-006-tr.html)	Bearings, Main (/qs3/pubsys2/xml/en/procedures/56/56-001-006-tr.html)
56-001-016-tr (/qs3/pubsys2/xml/en/procedures/56/56-001-016-tr.html)	Crankshaft (/qs3/pubsys2/xml/en/procedures/56/56-001-016-tr.html)

Last Modified: 19-Dec-2007