



Technical Service Bulletin

Technical Service Bulletin: tsb102657

Released Date: 19-Jun-2008

Complete Replacement, Cylinder Block Procedure

Complete Replacement, Cylinder Block Procedure

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic releases common Procedure 001-026 (Cylinder Block) for the QSK45, QSK60, QSK45G, and QSK60G engines.

Related Procedures

102-001-026
(/qs3/pubsys2/xml/en/procedures/102/102-001-026.html)

Cylinder Block
(/qs3/pubsys2/xml/en/procedures/102/102-001-026.html)

Last Modified: 19-Jun-2008