



Technical Service Bulletin

Technical Service Bulletin: tsb102666

Released Date: 05-Mar-2008

New Procedure, Piston and Cylinder Liner

New Procedure, Piston and Cylinder Liner

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic introduces new Procedure 001-045 (Piston and Cylinder Liner) to the QSK45 and QSK60 Service Manual, Bulletin 4021530.

The procedure includes the removal and installation steps required for the new straight split connecting rod used in QSK45 and QSK60 engines. The cylinder liner, piston and connecting rod **must** be removed as a complete assembly.

Related Procedures

56-001-045-tr
(/qs3/pubsys2/xml/en/procedures/56/56-001-045-tr.html)

Piston and Cylinder Liner
(/qs3/pubsys2/xml/en/procedures/56/56-001-045-tr.html)

Last Modified: 05-Mar-2008