



Technical Service Bulletin

Technical Service Bulletin: tsb102668

Released Date: 25-Feb-2008

Revision, Remove Step, Crankshaft Procedure

Revision, Remove Step, Crankshaft Procedure

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic revises the Remove Step in Procedure 001-016 (Crankshaft) in Section 1, of the QSK45 and QSK60 Service Manual, Bulletin 4021530. The Main Bearing Cap Puller service tool number has been revised.

Related Procedures

56-001-016

(/qs3/pubsys2/xml/en/procedures/56/56-001-016.html)

Crankshaft

(/qs3/pubsys2/xml/en/procedures/56/56-001-016.html)

Last Modified: 25-Feb-2008