



Technical Service Bulletin

Technical Service Bulletin: tsb102719

Released Date: 12-Mar-2008

Revision, Multiple Sections, Piston Cooling Nozzle Procedure

Revision, Multiple Sections, Piston Cooling Nozzle Procedure

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic revises multiple sections of Procedure 001-046 (Piston Cooling Nozzle). There are now two types of piston cooling nozzles available for QSK45 and QSK60 engines. This procedure has been updated to include information to distinguish between the two nozzle types.

Related Procedures

56-001-046-tr
(/qs3/pubsys2/xml/en/procedures/56/56-001-046-tr.html)

Piston Cooling Nozzle
(/qs3/pubsys2/xml/en/procedures/56/56-001-046-tr.html)

Last Modified: 12-Mar-2008