



Technical Service Bulletin

Technical Service Bulletin: tsb102720

Released Date: 19-Mar-2008

Revision, Install Section, Crosshead Procedure and Revision, Clean and Inspect for Reuse Section, Cylinder Head Procedure

Revision, Install Section, Crosshead Procedure and Revision, Clean and Inspect for Reuse Section, Cylinder Head Procedure

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts topic revises two procedures in the QSK45 and QSK60 Service Manual:

002-001 (Crosshead) in Section 2, the Install section, valve stem tip check has been added.

002-004 (Cylinder Head) in Section 2, the Inspect for Reuse section, valve stem tip check has been added.

Related Procedures

56-002-001-tr (/qs3/pubsys2/xml/en/procedures/56/56-002-001-tr.html)	Crosshead (/qs3/pubsys2/xml/en/procedures/56/56-002-001-tr.html)
56-002-004-tr (/qs3/pubsys2/xml/en/procedures/56/56-002-004-tr.html)	Cylinder Head (/qs3/pubsys2/xml/en/procedures/56/56-002-004-tr.html)

Last Modified: 19-Mar-2008