



Technical Service Bulletin

Technical Service Bulletin: tsb102728

Released Date: 25-Mar-2008

Release of (Gear Housing, Front) and Cylinder Block Liner Bore Concentricity Procedures

Release of (Gear Housing, Front) and Cylinder Block Liner Bore Concentricity Procedures

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic releases Procedure 84-001-033 (Gear Housing, Front) for the QSK45G and QSK60G engines and common Procedure 102-001-070 (Cylinder Block Liner Bore Concentricity) for the QSK45, QSK60, QSK45G, and QSK60G engines.

Related Procedures

102-001-070 (/qs3/pubsys2/xml/en/procedures/102/102-001-070.html)	Cylinder Block Liner Bore Concentricity (/qs3/pubsys2/xml/en/procedures/102/102-001-070.html)
84-001-033-tr (/qs3/pubsys2/xml/en/procedures/84/84-001-033-tr.html)	Gear Housing, Front (/qs3/pubsys2/xml/en/procedures/84/84-001-033-tr.html)

Last Modified: 25-Mar-2008