



Technical Service Bulletin

Technical Service Bulletin: tsb102897

Released Date: 06-Jun-2008

(Fan Hub, Belt Driven) Procedure, Multiple Section Revisions

(Fan Hub, Belt Driven) Procedure, Multiple Section Revisions

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic revised Procedure 008-036 (Fan Hub, Belt Driven) in the QSK45 and QSK60 Service Manual, Bulletin 4021530, with the removal of the K38 and K50 manual sections from this procedure.

Related Procedures

56-008-036-tr
(/qs3/pubsys2/xml/en/procedures/56/56-008-036-tr.html)

Fan Hub, Belt Driven
(/qs3/pubsys2/xml/en/procedures/56/56-008-036-tr.html)

Last Modified: 06-Jun-2008