



Technical Service Bulletin

Technical Service Bulletin: tsb102936

Released Date: 11-Jul-2008

Revision, Cylinder Liner Procedure

Revision, Cylinder Liner Procedure

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic revises Procedure 001-028 (Cylinder Liner) in the QSK45 and QSK60 Service Manual, Bulletin 4021530. The Remove step has been revised to change the recommended cylinder liner removal service tool to Part Number 3163745.

Related Procedures

56-001-028-tr
(/qs3/pubsys2/xml/en/procedures/56/56-001-028-tr.html)

Cylinder Liner
(/qs3/pubsys2/xml/en/procedures/56/56-001-028-tr.html)

Last Modified: 11-Jul-2008