



Technical Service Bulletin

Technical Service Bulletin: tsb102948

Released Date: 23-Jul-2008

Additional Inspection Steps, Two Procedures and One Symptom Tree

Additional Inspection Steps, Two Procedures and One Symptom Tree

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic revises Troubleshooting Symptom Tree t105 (Lubricating Oil Pressure Low) in Section TS, Procedure 007-013 (Lubricating Oil Filter (Spin-On)) and Procedure 007-067 (Eliminator Filter) in Section 7 of the Service Manual, QSK45 and QSK60, Bulletin 4021530. A change was made to inspect the lubricating pump idler shaft and gear in the Inspect section if debris is found.

Note : This is a product improvement and is not subject to campaign.

Lubricating Oil Pressure Low

Related Procedures

56-007-013-tr (/qs3/pubsys2/xml/en/procedures/56/56-007-013-tr.html)	Lubricating Oil Filter (Spin-On) (/qs3/pubsys2/xml/en/procedures/56/56-007-013-tr.html)
56-007-067-tr (/qs3/pubsys2/xml/en/procedures/56/56-007-067-tr.html)	Eliminator Filter (/qs3/pubsys2/xml/en/procedures/56/56-007-067-tr.html)

Last Modified: 23-Jul-2008