



Technical Service Bulletin

Technical Service Bulletin: tsb103097

Released Date: 30-Sep-2008

Piston and Connecting Rod Assembly Procedure, Remove Section Revision; Connecting Rod Procedure, Measure Section Revision

Piston and Connecting Rod Assembly Procedure, Remove Section Revision; Connecting Rod Procedure, Measure Section Revision

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic revises Procedures 001-054 (Piston and Connecting Rod Assembly) and 001-014 (Connecting Rod) in Section 1 of the Service Manual, QSK45 and QSK60, Bulletin 4021530 (</qs3/portal/manualviewer.html?path=/qs3/pubsys2/xml/en/outlines/4021530.html>).

The piston and connecting rod assembly procedure was revised for split angle split connecting rods **only** and the connecting rod procedure torque values were revised.

Note : This is a product improvement and is not subject to campaign.

Related Procedures

56-001-014 (/qs3/pubsys2/xml/en/procedures/56/56-001-014.html)	Connecting Rod (/qs3/pubsys2/xml/en/procedures/56/56-001-014.html)
56-001-054-tr (/qs3/pubsys2/xml/en/procedures/56/56-001-054-tr.html)	Piston and Connecting Rod Assembly (/qs3/pubsys2/xml/en/procedures/56/56-001-054-tr.html)

Last Modified: 30-Sep-2008

