



Technical Service Bulletin

Technical Service Bulletin: tsb103098

Released Date: 21-Nov-2008

Fuel Manifold (Supply) Procedure, Multiple Section Revisions

Fuel Manifold (Supply) Procedure, Multiple Section Revisions

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic revises multiple sections in Procedure 006-022 (Fuel Manifold (Supply)) in Section 6 of the QSK 45 and QSK 60 Series Service Manual, Bulletin 4021530.

Related Procedures

56-006-022-tr
(/qs3/pubsys2/xml/en/procedures/56/56-006-022-tr.html)

Fuel Manifold (Supply)
(/qs3/pubsys2/xml/en/procedures/56/56-006-022-tr.html)

Last Modified: 21-Nov-2008