



Technical Service Bulletin

Technical Service Bulletin: tsb103129

Released Date: 12-Dec-2008

Piston and Cylinder Liner Procedure, Multiple Section Revisions

Piston and Cylinder Liner Procedure, Multiple Section Revisions

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic revises Procedure 001-045 (Piston and Cylinder Liner) in Section 1 of the QSK45 and QSK60 Service Manual, Bulletin 4021530.

An additional cylinder liner removal tool and related usage has been added, in addition to the inclusion of a straight torque value for tightening the connecting rods when working through the hand hole covers.

Related Procedures

56-001-045-tr
(/qs3/pubsys2/xml/en/procedures/56/56-001-045-tr.html)

Piston and Cylinder Liner
(/qs3/pubsys2/xml/en/procedures/56/56-001-045-tr.html)

Last Modified: 12-Dec-2008