



Technical Service Bulletin

Technical Service Bulletin: tsb103132

Released Date: 10-Oct-2008

Piston Procedure, Clean and Inspect for Reuse Section Revision

Piston Procedure, Clean and Inspect for Reuse Section Revision

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic revises Procedure 001-043 (Piston) in the QSK45 and QSK60 Service Manual, Bulletin 4021530. The revision includes new minimum reuse limits for the top piston ring groove in the Ring Groove Wear Limits table. The top ring groove wear limits have been modified to a minimum specification of 159.10 mm [6.264 in].

Related Procedures

56-001-043-tr
(/qs3/pubsys2/xml/en/procedures/56/56-001-043-tr.html)

Piston
(/qs3/pubsys2/xml/en/procedures/56/56-001-043-tr.html)

Last Modified: 10-Oct-2008