



Technical Service Bulletin

Technical Service Bulletin: tsb103220

Released Date: 21-Nov-2008

Fan Drive Idler Arm Assembly Procedure, Assembly Section Revision

Fan Drive Idler Arm Assembly Procedure, Assembly Section Revision

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This purpose of this Service/Parts Topic is revise the assembly section in Procedure 008-029 (Fan Drive Idler Arm Assembly). The assembly torque specifications in the summary now match the specifications in the step.

Related Procedures

56-008-029-tr
(/qs3/pubsys2/xml/en/procedures/56/56-008-029-tr.html)

Fan Drive Idler Arm Assembly
(/qs3/pubsys2/xml/en/procedures/56/56-008-029-tr.html)

Last Modified: 21-Nov-2008