



Technical Service Bulletin

Technical Service Bulletin: tsb103221

Released Date: 07-Jan-2009

Pre-Lubricating Oil Pump Procedure, Install Section Revisions

Pre-Lubricating Oil Pump Procedure, Install Section Revisions

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic revises the mounting bracket capscrew torque value in the Install section of Procedure 007-063 (Pre-Lubricating Oil Pump).

Related Procedures

56-007-063
(/qs3/pubsys2/xml/en/procedures/56/56-007-063.html)

Pre-Lubricating Oil Pump
(/qs3/pubsys2/xml/en/procedures/56/56-007-063.html)

Last Modified: 07-Jan-2009