



Technical Service Bulletin

Technical Service Bulletin: tsb103265

Released Date: 17-Dec-2008

Multiple Group 01 Procedure Revisions

Multiple Group 01 Procedure Revisions

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic documents revisions to Procedures 001-026 (Cylinder Block), 001-037 (Idler Gear, Camshaft (Left Bank)), 001-038 (Idler Gear, Camshaft (Right Bank)), 001-039 (Idler Gear, Hydraulic Pump), and 001-040 (Idler Gear, Water Pump). The revisions include specifications changes in the Clean and Inspect for Reuse section.

Related Procedures

102-001-026 (/qs3/pubsys2/xml/en/procedures/102/102-001-026.html)	Cylinder Block (/qs3/pubsys2/xml/en/procedures/102/102-001-026.html)
56-001-037-tr (/qs3/pubsys2/xml/en/procedures/56/56-001-037-tr.html)	Idler Gear, Camshaft (Left Bank) (/qs3/pubsys2/xml/en/procedures/56/56-001-037-tr.html)
56-001-038-tr (/qs3/pubsys2/xml/en/procedures/56/56-001-038-tr.html)	Idler Gear, Camshaft (Right Bank) (/qs3/pubsys2/xml/en/procedures/56/56-001-038-tr.html)
56-001-039-tr (/qs3/pubsys2/xml/en/procedures/56/56-001-039-tr.html)	Idler Gear, Hydraulic Pump (/qs3/pubsys2/xml/en/procedures/56/56-001-039-tr.html)
56-001-040-tr (/qs3/pubsys2/xml/en/procedures/56/56-001-040-tr.html)	Idler Gear, Water Pump (/qs3/pubsys2/xml/en/procedures/56/56-001-040-tr.html)

