



Technical Service Bulletin

Technical Service Bulletin: tsb103274

Released Date: 05-Jan-2009

(Air Leaks, Compressed Air System) Procedure Addition

(Air Leaks, Compressed Air System) Procedure Addition

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This purpose of this Service/Parts Topic is to revise the Maintenance Schedule in order to include Procedure 012-019 (Air Leaks, Compressed Air System) into Section 4 of the Operation and Maintenance Manual QSK45 and QSK60 Series Engines, Bulletin 3666260, so that it is checked on a regular basis. This procedure needs to be performed for all compressed air systems to prevent carbon build-up and possible failure of the compressed air system.

Related Procedures

56-102-002-om
(/qs3/pubsys2/xml/en/procedures/56/56-102-002-om.html)

Maintenance Schedule
(/qs3/pubsys2/xml/en/procedures/56/56-102-002-om.html)

Last Modified: 05-Jan-2009