



Technical Service Bulletin

Technical Service Bulletin: tsb103289

Released Date: 16-Feb-2009

Gear Cover Trunion Sleeve, New Procedure

Gear Cover Trunion Sleeve, New Procedure

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic introduces a new Procedure 001-030 (Gear Cover Trunion Sleeve) in Section 1, in the QSK45 and QSK60 Service Manual, Bulletin 4021530.

Related Procedures

56-001-030
(/qs3/pubsys2/xml/en/procedures/56/56-001-030.html)

Gear Cover Trunion Sleeve
(/qs3/pubsys2/xml/en/procedures/56/56-001-030.html)

Last Modified: 16-Feb-2009