



Technical Service Bulletin

Technical Service Bulletin: tsb103306

Released Date: 16-Jan-2009

Fuel Pump Procedure, Multiple Section Revisions

Fuel Pump Procedure, Multiple Section Revisions

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic revises Procedure 005-016 in Section 5 to include information about painting the fuel pump after it is installed.

Related Procedures

56-005-016
(/qs3/pubsys2/xml/en/procedures/56/56-005-016.html)

Fuel Pump
(/qs3/pubsys2/xml/en/procedures/56/56-005-016.html)

Last Modified: 16-Jan-2009