



Technical Service Bulletin

Technical Service Bulletin: tsb103307

Released Date: 16-Jan-2009

Injector Procedure, Multiple Section Revisions

Injector Procedure, Multiple Section Revisions

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic revises Procedure 006-026 (Injector) in Section 6 to include information about painting the exposed portion of the electronically actuated injector to prevent the formation of rust and corrosion.

Related Procedures

56-006-026-tr
(/qs3/pubsys2/xml/en/procedures/56/56-006-026-tr.html)

Injector
(/qs3/pubsys2/xml/en/procedures/56/56-006-026-tr.html)

Last Modified: 16-Jan-2009