



Technical Service Bulletin

Technical Service Bulletin: tsb103354

Released Date: 06-Mar-2009

Camshaft Bushings Procedure, Major Revision

Camshaft Bushings Procedure, Major Revision

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic revises multiple sections of Procedure 001-010 (Camshaft Bushings).

Related Procedures

56-001-010-tr
(/qs3/pubsys2/xml/en/procedures/56/56-001-010-tr.html)

Camshaft Bushings
(/qs3/pubsys2/xml/en/procedures/56/56-001-010-tr.html)

Last Modified: 06-Mar-2009