



Technical Service Bulletin

Technical Service Bulletin: tsb103361

Released Date: 18-Feb-2009

(Exhaust Manifold, Dry) Procedure, Install Section Revision

(Exhaust Manifold, Dry) Procedure, Install Section Revision

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic revises the Install Section of Procedure 011-007 (Exhaust Manifold, Dry) in the Service Manual, QSK45 and QSK60, Bulletin 4021530. The installation of the lockplates has been revised.

Related Procedures

56-011-007-tr
(/qs3/pubsys2/xml/en/procedures/56/56-011-007-tr.html)

Exhaust Manifold, Dry
(/qs3/pubsys2/xml/en/procedures/56/56-011-007-tr.html)

Last Modified: 18-Feb-2009