



# Technical Service Bulletin

---

|                                                                       |                            |
|-----------------------------------------------------------------------|----------------------------|
| Technical Service Bulletin: tsb103392                                 | Released Date: 27-Feb-2009 |
| Cylinder Head Procedure, Clean and Inspect for Reuse Section Revision |                            |

## Cylinder Head Procedure, Clean and Inspect for Reuse Section Revision

### Warranty Statement

---

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

### Contents

---

This Service/Parts Topic adds a step to the Clean and Inspect for Reuse section of Procedure 002-004 (Cylinder Head). A check for cracked exhaust port divider has been added.

### Related Procedures

---

|                                                                         |                                                                         |
|-------------------------------------------------------------------------|-------------------------------------------------------------------------|
| 56-002-004-tr<br>(/qs3/pubsys2/xml/en/procedures/56/56-002-004-tr.html) | Cylinder Head<br>(/qs3/pubsys2/xml/en/procedures/56/56-002-004-tr.html) |
|-------------------------------------------------------------------------|-------------------------------------------------------------------------|

---

Last Modified: 27-Feb-2009

---