



Technical Service Bulletin

Technical Service Bulletin: tsb103401

Released Date: 13-Mar-2009

(Bearings, Main) Procedure, Remove Section Revision and Crankshaft Procedure, Multiple Section Additions

(Bearings, Main) Procedure, Remove Section Revision and Crankshaft Procedure, Multiple Section Additions

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic revises procedures 001-006 (Bearings, Main) and 001-016 (Crankshaft) for the QSK45 and QSK60 engines.

The Remove section has been revised for procedure 001-006 in Section 1. Preparatory and Finishing sections have been added to procedure 001-016 in Section 1.

Related Procedures

56-001-006-tr (/qs3/pubsys2/xml/en/procedures/56/56-001-006-tr.html)	Bearings, Main (/qs3/pubsys2/xml/en/procedures/56/56-001-006-tr.html)
56-001-016-tr (/qs3/pubsys2/xml/en/procedures/56/56-001-016-tr.html)	Crankshaft (/qs3/pubsys2/xml/en/procedures/56/56-001-016-tr.html)

Last Modified: 13-Mar-2009