



Technical Service Bulletin

Technical Service Bulletin: tsb103420

Released Date: 17-Mar-2009

Cylinder Block and Liner Seats Procedure, Major Revision

Cylinder Block and Liner Seats Procedure, Major Revision

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic revises multiple sections of Procedure 001-027 (Cylinder Block and Liner Seats).

Related Procedures

56-001-027
(/qs3/pubsys2/xml/en/procedures/56/56-001-027.html)

Cylinder Block and Liner Seats
(/qs3/pubsys2/xml/en/procedures/56/56-001-027.html)

Last Modified: 17-Mar-2009