



Technical Service Bulletin

Technical Service Bulletin: tsb103421

Released Date: 08-Apr-2009

Cylinder Block Procedure, Major Revision, and Removal of Cylinder Liner Bore Concentricity Procedure

Cylinder Block Procedure, Major Revision, and Removal of Cylinder Liner Bore Concentricity Procedure

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic introduces a complete revision of Procedure 001-026 (Cylinder Block) and removes Procedure 001-070 (Cylinder Liner Bore Concentricity).

Related Procedures

102-001-026
(/qs3/pubsys2/xml/en/procedures/102/102-001-026.html)

Cylinder Block
(/qs3/pubsys2/xml/en/procedures/102/102-001-026.html)

Last Modified: 08-Apr-2009